


29 408 DL0 ATRIO FIVE-HOLE BATH COMBINATION



SPARE PARTS, november 2022 – now

- 1: Cross handle bath (Spare part-nr. 14217DL0)
 - 2: Escutcheon (Spare part-nr. 101351DL00)
 - 3: Ceramic headpart 3/4" (Spare part-nr. 45888000)
 - 4: Valve seat 3/4" (Spare part-nr. 45345000)
 - 5: Replacement kit for shank fastening (Spare part-nr. 45444000)
 - 6: Connecting hose (Spare part-nr. 48019000)
 - 7: Spout (Spare part-nr. 101350DL00)
 - 7.1: Mousseur (Spare part-nr. 13926000)
 - 8: Connecting hose (Spare part-nr. 48018000)
 - 9: Ceramic headpart 3/4" (Spare part-nr. 45887000)
 - 10: Dirt strainer (Spare part-nr. 0700200M)
 - 11: Cone nut (Spare part-nr. 08864DL0)
 - 12: Compression spring (Spare part-nr. 00869000)
 - 13: Metal shower hose (Spare part-nr. 28146000)
 - 14: Diverter knob (Spare part-nr. 48411DL0)
 - 15: Diverter (Spare part-nr. 45443000)
 - 15.1: Sealing washer $\varnothing 6 \times \varnothing 2$ (Spare part-nr. 0128300M)
 - 15.2: Sealing washer (Spare part-nr. 0120500M)
 - 16: Non-return valve (Spare part-nr. 08565000)
 - 17: Connecting hose (Spare part-nr. 07300000)
 - 18: Socket spanner (Spare part-nr. 19332000)*
- * Optional accessories